



XGPS150A

Universal Bluetooth GPS Receiver

for iPad, iPod touch, iPhone and Android tablets

Firmware Upgrade Guide ver. 1.3.4

If your XGPS150/XGPS150A has firmware version 1.0.34 & your Windows version is not Windows 10, the update may not work. If you have any questions, please contact Dual customer support (cs@dualav.com) before attempting the update.

A. You will need

- XGPS150 or XGPS150A (hereafter XGPS150)
- USB-to-mini-USB cable
- Computer running Windows OS (XP and later) with an available USB port




If you're using a laptop, please proceed with the update with the power cord plugged in to ensure that the computer does not go to sleep/hibernation



B. Update Instructions

1. Go to Dual XGPS150A Firmware page (<http://gps.dualav.com/explore-by-product/xgps150a/#tabs-8>)
2. Download the XGPS150 Firmware Update Pack (v1.3.4) zip file.
3. Unzip the file and you will see XGPS150 Firmware Update Pack folder.
4. Open XGPS150 Firmware Update Pack folder, you will see three items.



PL2303_Driver_releasenote



PL2303_Prolific_DriverInstaller_v1417



xgps150fw-v1.3.4

5. Install the driver for XGPS150A (PL2303_Prolific_DriverInstaller). After installation, restart your computer if prompted.




XGPS150A


Universal Bluetooth GPS Receiver

for iPad, iPod touch, iPhone and Android tablets

Firmware Upgrade Guide ver. 1.3.4



6. Open the XGPS150 Firmware Updater program (xgps150fw-v1.3.4) in the XGPS150 Firmware Update Pack folder.





XGPS150A

Universal Bluetooth GPS Receiver


for iPad, iPod touch, iPhone and Android tablets

Firmware Upgrade Guide ver. 1.3.4

7. Move the XGPS150's Switch towards the USB port. Connect XGPS150 to the PC.



8. To update the firmware, **XGPS150** must be connected to the computer while the Power is turned off. Press and hold the Power Button until the Bluetooth LED (Blue) and GPS LED (Green) are turned OFF.



9. In the XGPS150 Firmware Updater program, click "Find and Program XGPS150" button. The program will automatically update your XGPS150. When you see "XGPS150 FIRMWARE UPDATE DONE" message at the bottom of the XGPS150 Firmware Updater program, close the program and unplug your XGPS150



IMPORTANT NOTE: Do not disconnect your XGPS150 during the update!!!







XGPS150A

Universal Bluetooth GPS Receiver

for iPad, iPod touch, iPhone and Android tablets

Firmware Upgrade Guide ver. 1.3.4



Troubleshooting:

- If XGPS150 Firmware Updater can't locate your XGPS150 try the following:
 - a) Reinstall the XGPS150 Driver
 - b) Make sure that the XGPS150 is OFF when connected to PC
 - c) Restart the computer
- If the XGPS150 Firmware Updater program gets stuck while updating, contact Dual customer service:

Email: cs@dualav.com

Toll-free (U.S. only): **1-866-382-5476**

(Monday – Friday, 9AM – 5PM EST)

Thank you for using Dual XGPS150!